



133

Work area

BLOOMFIELD DR

45

510-63.4

5110

▲ 53 ROLLINGWOOD CIR

Pipe and headwall
deemed deficient

New pipe and armour stone
headwall

ROLLINGWOOD CIR